

Tool Kit, Supplemental, Explosive Ordnance Disposal: Field Maintenance

SC: **1385-95-A03**
NSN: **1385-01-095-5221, 1385-01-526-0332**
LIN: **T57126**

System Description

NSN: 1385-01-526-0332 replaces NSN: 1385-01-095-5221. This kit has been replaced by the EOD Response Kit, LIN T00280, NSN 138-501-487-8701. This kit contains basic and common hand tools for Light Teams and heavy Teams: considered ASIOE to the BEOD. The kit consolidated 5 separate tool sets into 1 - eliminated duplication and weight (500 lbs). It's organized into separately packaged mission modules.

This system is not currently in reset.

Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

Reset Strategy

NSN: 1385-01-526-0332 replaces NSN: 1385-01-095-5221
This Team Supplemental Kit is subject to the Warranty /Replacement Program. All components to this kit should be reset by the using unit via the Warranty/Replacement Program. Contact Item manager to report battle loss of kit if necessary and request disposition.

Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.

Reset Responsibility

Unit

Reset Location

This system is not currently in reset.

- Contact Information -

877.4.PMSKOT (877.476.7568)
rock-pm-skot@conus.army.mil